

CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20191120
Issue Date 2022-JUNE-27

Issued to: TRACO ELECTRONIC AG
Sihlbruggstrasse 111
Baar, 6340 Switzerland

**This certificate confirms that
representative samples of**

COMPONENT - POWER SUPPLIES FOR USE WITH
AUDIO/VIDEO, INFORMATION AND COMMUNICATION
TECHNOLOGY EQUIPMENT

See addendumn page for Models/Product

Have been evaluated by UL in accordance with the
component requirements in the Standard(s) indicated on
this Certificate. UL Recognized components are incomplete
in certain constructional features or restricted in
performance capabilities and are intended for installation in
complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety:

UL 62368-1, - (Audio/video, information and communication
technology equipment Part 1: Safety requirements)
CAN/CSA C22.2 No. 62368-1, CAN/CSA C22.2 No. 62368-
1-14 - (Audio/video, information and communication
technology equipment Part 1: Safety requirements)


Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for
additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification
report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized
Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing
surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified
and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product. |



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact UL Customer Service at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE


Certificate Number E188913
Report Reference E188913-20191120
Issue Date 2022-JUNE-27

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Models TEN 40-1210Ezzzzzz, TEN 40-1211Ezzzzzz, TEN 40-1212Ezzzzzz, TEN 40-1213Ezzzzzz, TEN 40-1215Ezzzzzz, TEN 40-1222Ezzzzzz, TEN 40-1223Ezzzzzz, TEN 40-1225Ezzzzzz, TEN 40-2410Ezzzzzz, TEN 40-2411Ezzzzzz, TEN 40-2412Ezzzzzz, TEN 40-2413Ezzzzzz, TEN 40-2415Ezzzzzz, TEN 40-2422Ezzzzzz, TEN 40-2423Ezzzzzz, TEN 40-2425Ezzzzzz, TEN 40-4810Ezzzzzz, TEN 40-4811Ezzzzzz, TEN 40-4812Ezzzzzz, TEN 40-4813Ezzzzzz, TEN 40-4815Ezzzzzz, TEN 40-4822Ezzzzzz, TEN 40-4823Ezzzzzz, TEN 40-4825Ezzzzzz, TEN 40-2410WIEzzzzzz, TEN 40-2411WIEzzzzzz, TEN 40-2412WIEzzzzzz, TEN 40-2413WIEzzzzzz, TEN 40-2415WIEzzzzzz, TEN 40-2422WIEzzzzzz, TEN 40-2423WIEzzzzzz, TEN 40-2425WIEzzzzzz, TEN 40-4810WIEzzzzzz, TEN 40-4811WIEzzzzzz, TEN 40-4812WIEzzzzzz, TEN 40-4813WIEzzzzzz, TEN 40-4815WIEzzzzzz, TEN 40-4822WIEzzzzzz, TEN 40-4823WIEzzzzzz, TEN 40-4825WIEzzzzzz, TEP 100-3611UIRzzzzzz, TEP 100-3612UIRzzzzzz, TEP 100-3613UIRzzzzzz, TEP 100-3615UIRzzzzzz, TEP 100-3616UIRzzzzzz, TEP 100-3618UIRzzzzzz, TEP 100-36153UIRzzzzzz, TEP 100-7211UIRzzzzzz, TEP 100-7212UIRzzzzzz, TEP 100-7213UIRzzzzzz, TEP 100-7215UIRzzzzzz, TEP 100-7216UIRzzzzzz, TEP 100-7218UIRzzzzzz, TEP 100-72153UIRzzzzzz, TEP 60-3611UIRzzzzzz, TEP 60-3612UIRzzzzzz, TEP 60-3613UIRzzzzzz, TEP 60-3615UIRzzzzzz, TEP 60-3616UIRzzzzzz, TEP 60-3618UIRzzzzzz, TEP 60-36153UIRzzzzzz, TEP 60-7211UIRzzzzzz, TEP 60-7212UIRzzzzzz, TEP 60-7213UIRzzzzzz, TEP 60-7215UIRzzzzzz, TEP 60-7216UIRzzzzzz, TEP 60-7218UIRzzzzzz, TEP 60-72153UIRzzzzzz, TEP 40-3611UIRzzzzzz, TEP 40-3612UIRzzzzzz, TEP 40-3613UIRzzzzzz, TEP 40-3615UIRzzzzzz, TEP 40-3616UIRzzzzzz, TEP 40-3618UIRzzzzzz, TEP 40-36153UIRzzzzzz, TEP 40-7211UIRzzzzzz, TEP 40-7212UIRzzzzzz, TEP 40-7213UIRzzzzzz, TEP 40-7215UIRzzzzzz, TEP 40-7216UIRzzzzzz, TEP 40-7218UIRzzzzzz, TEP 40-72153UIRzzzzzz, TRV 1-0510Maaaaaa, TRV 1-0511Maaaaaa, TRV 1-0512Maaaaaa, TRV 1-0513Maaaaaa, TRV 1-0521Maaaaaa, TRV 1-0522Maaaaaa, TRV 1-0523Maaaaaa, TRV 1-1210Maaaaaa, TRV 1-1211Maaaaaa, TRV 1-1212Maaaaaa, TRV 1-1213Maaaaaa, TRV 1-1221Maaaaaa, TRV 1-1222Maaaaaa, TRV 1-1223Maaaaaa, TRV 1-1510Maaaaaa, TRV 1-1511Maaaaaa, TRV 1-1512Maaaaaa, TRV 1-1513Maaaaaa, TRV 1-1521Maaaaaa, TRV 1-1522Maaaaaa, TRV 1-1523Maaaaaa, TRV 1-2410Maaaaaa, TRV 1-2411Maaaaaa, TRV 1-2412Maaaaaa, TRV 1-2413Maaaaaa, TRV 1-2421Maaaaaa, TRV 1-2422Maaaaaa, TRV 1-2423Maaaaaa, THN 20-2410WIRaaaaaa, THN 20-2411WIRaaaaaa, THN 20-2412WIRaaaaaa, THN 20-2413WIRaaaaaa, THN 20-2415WIRaaaaaa, THN 20-2422WIRaaaaaa,

Where z = alphanumeric, "-", "/" or blank for marketing purposes.
Where a = alphanumeric, "-", "/" or blank for marketing purposes.

(Continued on Next Page)



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20191120
Issue Date 2022-JUNE-27

Models THN 20-2423WIRaaaaaa, THN 20-2425WIRaaaaaa, THN 20-4810WIRaaaaaa, THN 20-4811BWIRaaaaaa, THN 20-4811WIRaaaaaa, THN 20-4812WIRaaaaaa, THN 20-4813WIRaaaaaa, THN 20-4815WIRaaaaaa, THN 20-4822WIRaaaaaa, THN 20-4823WIRaaaaaa, THN 20-4825WIRaaaaaa, THN 20-7210WIRaaaaaa, THN 20-7211BWIRaaaaaa, THN 20-7211WIRaaaaaa, THN 20-7212WIRaaaaaa, THN 20-7213WIRaaaaaa, THN 20-7215WIRaaaaaa, THN 20-7222WIRaaaaaa, THN 20-7223WIRaaaaaa, THN 20-7225WIRaaaaaa, THN 30-2410WIRaaaaaa, THN 30-2411WIRaaaaaa, THN 30-2412WIRaaaaaa, THN 30-2413WIRaaaaaa, THN 30-2415WIRaaaaaa, THN 30-2422WIRaaaaaa, THN 30-2423WIRaaaaaa, THN 30-2425WIRaaaaaa, THN 30-4810WIRaaaaaa, THN 30-4811WIRaaaaaa, THN 30-4812WIRaaaaaa, THN 30-4813WIRaaaaaa, THN 30-4815WIRaaaaaa, THN 30-4822WIRaaaaaa, THN 30-4823WIRaaaaaa, THN 30-4825WIRaaaaaa, TEN 10-11010WIRH, TEN 10-11011WIRH, TEN 10-11012WIRH, TEN 10-11013WIRH, TEN 10-11015WIRH, TEN 10-11021WIRH, TEN 10-11022WIRH, TEN 10-11023WIRH, TEN 3-11010WIRH, TEN 3-11011WIRH, TEN 3-11012WIRH, TEN 3-11013WIRH, TEN 3-11015WIRH, TEN 3-11021WIRH, TEN 3-11022WIRH, TEN 3-11023WIRH, TEN 6-11010WIRH, TEN 6-11011WIRH, TEN 6-11012WIRH, TEN 6-11013WIRH, TEN 6-11015WIRH, TEN 6-11021WIRH, TEN 6-11022WIRH, TEN 6-11023WIRH, TEN 8-1210zzzzzz, TEN 8-1211zzzzzz, TEN 8-1212zzzzzz, TEN 8-1213zzzzzz, TEN 8-1221zzzzzz, TEN 8-1222zzzzzz, TEN 8-1223zzzzzz, TEN 8-2410zzzzzz, TEN 8-2411zzzzzz, TEN 8-2412zzzzzz, TEN 8-2413zzzzzz, TEN 8-2421zzzzzz, TEN 8-2422zzzzzz, TEN 8-2423zzzzzz, TEN 8-4810zzzzzz, TEN 8-4811zzzzzz, TEN 8-4812zzzzzz, TEN 8-4813zzzzzz, TEN 8-4821zzzzzz, TEN 8-4822zzzzzz, TEN 8-4823zzzzzz, THD 12-1209zzzzzz, THD 12-1210zzzzzz, THD 12-1211zzzzzz, THD 12-1212zzzzzz, THD 12-1213zzzzzz, THD 12-1221zzzzzz, THD 12-1222zzzzzz, THD 12-1223zzzzzz, THD 12-2409zzzzzz, THD 12-2410zzzzzz, THD 12-2411zzzzzz, THD 12-2412zzzzzz, THD 12-2413zzzzzz, THD 12-2421zzzzzz, THD 12-2422zzzzzz, THD 12-2423zzzzzz, THD 12-4809zzzzzz, THD 12-4810zzzzzz, THD 12-4811zzzzzz, THD 12-4812zzzzzz, THD 12-4813zzzzzz, THD 12-4821zzzzzz, THD 12-4822zzzzzz, THD 12-4823zzzzzz, THD 12-2410Wlzzzzzz, THD 12-2411Wlzzzzzz, THD 12-2412Wlzzzzzz, THD 12-2413Wlzzzzzz, THD 12-2421Wlzzzzzz, THD 12-2422Wlzzzzzz, THD 12-2423Wlzzzzzz, THD 12-4810Wlzzzzzz, THD 12-4811Wlzzzzzz, THD 12-4812Wlzzzzzz, THD 12-4813Wlzzzzzz, THD 12-4821Wlzzzzzz, THD 12-4822Wlzzzzzz, THD 12-4823Wlzzzzzz, TEN 8-2410Wlzzzzzz, TEN 8-2411Wlzzzzzz.

Where z = alphanumeric, "-", "/" or blank for marketing purposes.

Where a = alphanumeric, "-", "/" or blank for marketing purposes.

(Continued on Next Page)



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20191120
Issue Date 2022-JUNE-27

Models TEN 8-2412Wlzzzzzz, TEN 8-2413Wlzzzzzz, TEN 8-2421Wlzzzzzz, TEN 8-2422Wlzzzzzz, TEN 8-2423Wlzzzzzz, TEN 8-4810Wlzzzzzz, TEN 8-4811Wlzzzzzz, TEN 8-4812Wlzzzzzz, TEN 8-4813Wlzzzzzz, TEN 8-4821Wlzzzzzz, TEN 8-4822Wlzzzzzz, TEN 8-4823Wlzzzzzz, TEN 8-7210Wlzzzzzz, TEN 8-7211Wlzzzzzz, TEN 8-7212Wlzzzzzz, TEN 8-7213Wlzzzzzz, TEN 8-7221Wlzzzzzz, TEN 8-7222Wlzzzzzz, TEN 8-7223Wlzzzzzz, TEP 100-7210WIRzzzzzz, TEP 100-7211WIRzzzzzz, TEP 100-7212WIRzzzzzz, TEP 100-7213WIRzzzzzz, TEP 100-7215WIRzzzzzz, TEP 100-7216WIRzzzzzz, TEP 100-7218WIRzzzzzz, TEP 160-1212zzzzzz, TEP 160-1213zzzzzz, TEP 160-1215zzzzzz, TEP 160-1216zzzzzz, TEP 160-2412zzzzzz, TEP 160-2413zzzzzz, TEP 160-2415zzzzzz, TEP 160-2416zzzzzz, TEP 160-4812zzzzzz, TEP 160-4813zzzzzz, TEP 160-4815zzzzzz, TEP 160-4816zzzzzz, TEP 160-2412WIRzzzzzz, TEP 160-2413WIRzzzzzz, TEP 160-2415WIRzzzzzz, TEP 160-2416WIRzzzzzz, TEP 160-4812WIRzzzzzz, TEP 160-4813WIRzzzzzz, TEP 160-4815WIRzzzzzz, TEP 160-4816WIRzzzzzz, TEP 160-7212WIRzzzzzz, TEP 160-7213WIRzzzzzz, TEP 160-7215WIRzzzzzz, TEP 160-7216WIRzzzzzz, TEP 200-1212zzzzzz, TEP 200-1213zzzzzz, TEP 200-1215zzzzzz, TEP 200-1216zzzzzz, TEP 200-2412zzzzzz, TEP 200-2413zzzzzz, TEP 200-2415zzzzzz, TEP 200-2416zzzzzz, TEP 200-2412WIRzzzzzz, TEP 200-2413WIRzzzzzz, TEP 200-2415WIRzzzzzz, TEP 200-2416WIRzzzzzz, TEP 200-4812WIRzzzzzz, TEP 200-4813WIRzzzzzz, TEP 200-4815WIRzzzzzz, TEP 200-4816WIRzzzzzz, TEP 200-7212WIRzzzzzz, TEP 200-7213WIRzzzzzz, TEP 200-7215WIRzzzzzz, TEP 200-7216WIRzzzzzz, TEP 100-2412WIRzzzzzz, TEP 100-2413WIRzzzzzz, TEP 100-2415WIRzzzzzz, TEP 100-2416WIRzzzzzz, TEP 100-4812WIRzzzzzz, TEP 100-4813WIRzzzzzz, TEP 100-4815WIRzzzzzz, TEP 100-4816WIRzzzzzz, TEP 160-1210zzzzzz, TEP 160-1211zzzzzz, TEP 160-2410zzzzzz, TEP 160-2411zzzzzz, TEP 160-4810zzzzzz, TEP 160-4811zzzzzz, TEP 160-2410WIRzzzzzz, TEP 160-2411WIRzzzzzz, TEP 160-4810WIRzzzzzz, TEP 160-4811WIRzzzzzz, TEP 160-7210WIRzzzzzz, TEP 160-7211WIRzzzzzz, TEP 200-1210zzzzzz, TEP 200-1211zzzzzz, TEP 200-2410zzzzzz, TEP 200-2411zzzzzz, TEP 200-4810zzzzzz, TEP 200-4811zzzzzz, TEP 200-2410WIRzzzzzz, TEP 200-2411WIRzzzzzz, TEP 200-4810WIRzzzzzz, TEP 200-4811WIRzzzzzz, TEP 200-7210WIRzzzzzz, TEP 200-7211WIRzzzzzz, TEP 100-2410WIRzzzzzz, TEP 100-2411WIRzzzzzz, TEP 100-4810WIRzzzzzz, TEP 100-4811WIRzzzzzz, TON 15-2410zzzzzz, TON 15-2411zzzzzz, TON 15-2412zzzzzz, TON 15-2413zzzzzz, TON 15-4810zzzzzz, TON 15-4811zzzzzz, TON 15-4812zzzzzz, TON 15-4813zzzzzz, TON 15-2410Wlzzzzzz, TON 15-2411Wlzzzzzz, TON 15-2412Wlzzzzzz, TON 15-2413Wlzzzzzz, TON 15-4810Wlzzzzzz, TON 15-4811Wlzzzzzz, TON 15-4812Wlzzzzzz, TON 15-4813Wlzzzzzz.

Where z = alphanumeric, "-", "/" or blank for marketing purposes.

(Continued on Next Page)



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20191120
Issue Date 2022-JUNE-27

Models TEN 20-2410WIRzzzzzz, TEN 20-2411WIRzzzzzz, TEN 20-2412WIRzzzzzz, TEN 20-2413WIRzzzzzz, TEN 20-2421WIRzzzzzz, TEN 20-2422WIRzzzzzz, TEN 20-2423WIRzzzzzz, TEN 20-4810WIRzzzzzz, TEN 20-4811WIRzzzzzz, TEN 20-4812WIRzzzzzz, TEN 20-4813WIRzzzzzz, TEN 20-4821WIRzzzzzz, TEN 20-4822WIRzzzzzz, TEN 20-4823WIRzzzzzz, TEN 20-7210WIRzzzzzz, TEN 20-7211WIRzzzzzz, TEN 20-7212WIRzzzzzz, TEN 20-7213WIRzzzzzz, TEN 20-7221WIRzzzzzz, TEN 20-7222WIRzzzzzz, TEN 20-7223WIRzzzzzz, TMR 6-0510zzzzzz, TMR 6-0511zzzzzz, TMR 6-0519zzzzzz, TMR 6-0512zzzzzz, TMR 6-0513zzzzzz, TMR 6-0515zzzzzz, TMR 6-0521zzzzzz, TMR 6-0522zzzzzz, TMR 6-0523zzzzzz, TMR 6-1210zzzzzz, TMR 6-1211zzzzzz, TMR 6-1219zzzzzz, TMR 6-1212zzzzzz, TMR 6-1213zzzzzz, TMR 6-1215zzzzzz, TMR 6-1221zzzzzz, TMR 6-1222zzzzzz, TMR 6-1223zzzzzz, TMR 6-2410zzzzzz, TMR 6-2411zzzzzz, TMR 6-2419zzzzzz, TMR 6-2412zzzzzz, TMR 6-2413zzzzzz, TMR 6-2415zzzzzz, TMR 6-2421zzzzzz, TMR 6-2422zzzzzz, TMR 6-2423zzzzzz, TMR 6-4810zzzzzz, TMR 6-4811zzzzzz, TMR 6-4819zzzzzz, TMR 6-4812zzzzzz, TMR 6-4813zzzzzz, TMR 6-4815zzzzzz, TMR 6-4821zzzzzz, TMR 6-4822zzzzzz, TMR 6-4823zzzzzz, TMR 6-0510HI zzzzzz, TMR 6-0511HI zzzzzz, TMR 6-0519HI zzzzzz, TMR 6-0512HI zzzzzz, TMR 6-0513HI zzzzzz, TMR 6-0515HI zzzzzz, TMR 6-0521HI zzzzzz, TMR 6-0522HI zzzzzz, TMR 6-0523HI zzzzzz, TMR 6-1210HI zzzzzz, TMR 6-1211HI zzzzzz, TMR 6-1219HI zzzzzz, TMR 6-1212HI zzzzzz, TMR 6-1213HI zzzzzz, TMR 6-1215HI zzzzzz, TMR 6-1221HI zzzzzz, TMR 6-1222HI zzzzzz, TMR 6-1223HI zzzzzz, TMR 6-2410HI zzzzzz, TMR 6-2411HI zzzzzz, TMR 6-2419HI zzzzzz, TMR 6-2412HI zzzzzz, TMR 6-2413HI zzzzzz, TMR 6-2415HI zzzzzz, TMR 6-2421HI zzzzzz, TMR 6-2422HI zzzzzz, TMR 6-2423HI zzzzzz, TMR 6-4810HI zzzzzz, TMR 6-4811HI zzzzzz, TMR 6-4819HI zzzzzz, TMR 6-4812HI zzzzzz, TMR 6-4813HI zzzzzz, TMR 6-4815HI zzzzzz, TMR 6-4821HI zzzzzz, TMR 6-4822HI zzzzzz, TMR 6-4823HI zzzzzz, TMR 9-1210Wlaaaaa, TMR 9-1211Wlaaaaa, TMR 9-1212Wlaaaaa, TMR 9-1213Wlaaaaa, TMR 9-1215Wlaaaaa, TMR 9-1221Wlaaaaa, TMR 9-1222Wlaaaaa, TMR 9-1223Wlaaaaa, TMR 9-2410Wlaaaaa, TMR 9-2411Wlaaaaa, TMR 9-2412Wlaaaaa, TMR 9-2413Wlaaaaa, TMR 9-2415Wlaaaaa, TMR 9-2421Wlaaaaa, TMR 9-2422Wlaaaaa, TMR 9-2423Wlaaaaa, TMR 9-4810Wlaaaaa, TMR 9-4811Wlaaaaa, TMR 9-4812Wlaaaaa, TMR 9-4813Wlaaaaa, TMR 9-4815Wlaaaaa, TMR 9-4821Wlaaaaa, TMR 9-4822Wlaaaaa, TMR 9-4823Wlaaaaa, TPI 50-105A-Jaaaaa, TPI 50-112A-Jaaaaa, TPI 50-115A-Jaaaaa, TPI 50-124A-Jaaaaa, TPI 50-136A-Jaaaaa, TPI 50-148A-Jaaaaa, TPI 50-153A-Jaaaaa, THM 60-2411Wlzzzzz, THM 60-2412Wlzzzzz, THM 60-2413Wlzzzzz, THM 60-2415Wlzzzzz, THM 60-2422Wlzzzzz, THM 60-2423Wlzzzzz, THM 60-4811Wlzzzzz, THM 60-4812Wlzzzzz, THM 60-4813Wlzzzzz, THM 60-4815Wlzzzzz, THM 60-4822Wlzzzzz, THM 60-4823Wlzzzzz, THN 30-7210WIRaaaaaa, THN 30-7211WIRaaaaaa, THN 30-7212WIRaaaaaa, THN 30-7213WIRaaaaaa, THN 30-7215WIRaaaaaa, THN 30-7222WIRaaaaaa, THN 30-7223WIRaaaaaa, THN 30-7225WIRaaaaaa.

Where z = alphanumeric, "-", "/" or blank for marketing purposes.

Where a = alphanumeric, "-", "/" or blank for marketing purposes.

(Continued on Next Page)



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20191120
Issue Date 2022-JUNE-27

Models TEN 40-2410WIR zzzzzz (a), TEN 40-2411WIR zzzzzz (a), TEN 40-2412WIR zzzzzz (a), TEN 40-2413WIR zzzzzz (a), TEN 40-2415WIR zzzzzz (a), TEN 40-2422WIR zzzzzz (a), TEN 40-2423WIR zzzzzz (a), TEN 40-2425WIR zzzzzz (a), TEN 40-4810WIR zzzzzz (a), TEN 40-4811WIR zzzzzz (a), TEN 40-4812WIR zzzzzz (a), TEN 40-4813WIR zzzzzz (a), TEN 40-4815WIR zzzzzz (a), TEN 40-4822WIR zzzzzz (a), TEN 40-4823WIR zzzzzz (a), TEN 40-4825WIR zzzzzz (a), TEN 40-7210WIR zzzzzz (a), TEN 40-7211WIR zzzzzz (a), TEN 40-7212WIR zzzzzz (a), TEN 40-7213WIR zzzzzz (a), TEN 40-7215WIR zzzzzz (a), TEN 40-7222WIR zzzzzz (a), TEN 40-7223WIR zzzzzz (a), TEN 40-7225WIR zzzzzz (a), TEN 60-1210N zzzzzz (a), TEN 60-1211N zzzzzz (a), TEN 60-1212N zzzzzz (a), TEN 60-1213N zzzzzz (a), TEN 60-1215N zzzzzz (a), TEN 60-1222N zzzzzz (a), TEN 60-1223N zzzzzz (a), TEN 60-1225N zzzzzz (a), TEN 60-2410N zzzzzz (a), TEN 60-2411N zzzzzz (a), TEN 60-2412N zzzzzz (a), TEN 60-2413N zzzzzz (a), TEN 60-2415N zzzzzz (a), TEN 60-2422N zzzzzz (a), TEN 60-2423N zzzzzz (a), TEN 60-2425N zzzzzz (a), TEN 60-4810N zzzzzz (a), TEN 60-4811N zzzzzz (a), TEN 60-4812N zzzzzz (a), TEN 60-4813N zzzzzz (a), TEN 60-4815N zzzzzz (a), TEN 60-4822N zzzzzz (a), TEN 60-4823N zzzzzz (a), TEN 60-4825N zzzzzz (a), TEN 60-2410WIN zzzzzz (a), TEN 60-2411WIN zzzzzz (a), TEN 60-2412WIN zzzzzz (a), TEN 60-2413WIN zzzzzz (a), TEN 60-2415WIN zzzzzz (a), TEN 60-2422WIN zzzzzz (a), TEN 60-2423WIN zzzzzz (a), TEN 60-2425WIN zzzzzz (a), TEN 60-4810WIN zzzzzz (a), TEN 60-4811WIN zzzzzz (a), TEN 60-4812WIN zzzzzz (a), TEN 60-4813WIN zzzzzz (a), TEN 60-4815WIN zzzzzz (a), TEN 60-4822WIN zzzzzz (a), TEN 60-4823WIN zzzzzz (a), TEN 60-4825WIN zzzzzz (a), TEP 75-2411Wlzzzzzz (a), TEP 75-2412Wlzzzzzz (a), TEP 75-2413Wlzzzzzz (a), TEP 75-2415Wlzzzzzz (a), TEP 75-2416Wlzzzzzz (a), TEP 75-2418Wlzzzzzz (a), TEP 75-4810Wlzzzzzz (a), TEP 75-4811Wlzzzzzz (a), TEP 75-4812Wlzzzzzz (a), TEP 75-4813Wlzzzzzz (a), TEP 75-4815Wlzzzzzz (a), TEP 75-4816Wlzzzzzz (a), TEP 75-4818Wlzzzzzz (a), TEP 100-1210zzzzzz (a), TEP 100-1211zzzzzz (a), TEP 100-1212zzzzzz (a), TEP 100-1213zzzzzz (a), TEP 100-1215zzzzzz (a), TEP 100-1216zzzzzz (a), TEP 100-1218zzzzzz (a), TEP 100-2410zzzzzz (a), TEP 100-2411zzzzzz (a), TEP 100-2412zzzzzz (a), TEP 100-2413zzzzzz (a), TEP 100-2415zzzzzz (a), TEP 100-2416zzzzzz (a), TEP 100-2418zzzzzz (a), TEP 100-4810zzzzzz (a), TEP 100-4811zzzzzz (a), TEP 100-4812zzzzzz (a), TEP 100-4813zzzzzz (a), TEP 100-4815zzzzzz (a), TEP 100-4816zzzzzz (a), TEP 100-4818zzzzzz (a).

(a) - Where z= alphanumeric, "-", "/" or blank for marketing purposes.

(Continued on Next Page)



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20191120
Issue Date 2022-JUNE-27

Models TEQ 75-2412WIR zzzzzz (a), TEQ 75-2415WIR zzzzzz (a), TEQ 75-2416WIR zzzzzz (a), TEQ 75-2418WIR zzzzzz (a), TEQ 75-4812WIR zzzzzz (a), TEQ 75-4815WIR zzzzzz (a), TEQ 75-4816WIR zzzzzz (a), TEQ 75-4818WIR zzzzzz (a), TEQ 75-7212WIR zzzzzz (a), TEQ 75-7215WIR zzzzzz (a), TEQ 75-7216WIR zzzzzz (a), TEQ 75-7218WIR zzzzzz (a), TEQ 100-2412WIR zzzzzz (a), TEQ 100-2415WIR zzzzzz (a), TEQ 100-2416WIR zzzzzz (a), TEQ 100-2418WIR zzzzzz (a), TEQ 100-4812WIR zzzzzz (a), TEQ 100-4815WIR zzzzzz (a), TEQ 100-4816WIR zzzzzz (a), TEQ 100-4818WIR zzzzzz (a), TEQ 100-7212WIR zzzzzz (a), TEQ 100-7215WIR zzzzzz (a), TEQ 100-7216WIR zzzzzz (a), TEQ 100-7218WIR zzzzzz (a), TEQ 160-4812WIR zzzzzz (a), TEQ 160-4815WIR zzzzzz (a), TEQ 160-4816WIR zzzzzz (a), TEQ 160-4818WIR zzzzzz (a), TEQ 160-7212WIR zzzzzz (a), TEQ 160-7215WIR zzzzzz (a), TEQ 160-7216WIR zzzzzz (a), TEQ 160-7218WIR zzzzzz (a), TEQ 200-4812WIR zzzzzz (a), TEQ 200-4815WIR zzzzzz (a), TEQ 200-4816WIR zzzzzz (a), TEQ 200-4818WIR zzzzzz (a), TEQ 200-7212WIR zzzzzz (a), TEQ 200-7215WIR zzzzzz (a), TEQ 200-7216WIR zzzzzz (a), TEQ 200-7218WIR zzzzzz (a).

(a) - Where z= alphanumeric, "-", "/" or blank for marketing purposes.

TEN 60-2411WIRzzzzzz (a), TEN 60-2412WIRzzzzzz (a), TEN 60-2413WIRzzzzzz (a), TEN 60-2415WIRzzzzzz (a), TEN 60-2418WIRzzzzzz (a), TEN 60-2422WIRzzzzzz (a), TEN 60-2423WIRzzzzzz (a), TEN 60-2425WIRzzzzzz (a), TEN 60-4811WIRzzzzzz (a), TEN 60-4812WIRzzzzzz (a), TEN 60-4813WIRzzzzzz (a), TEN 60-4815WIRzzzzzz (a), TEN 60-4818WIRzzzzzz (a), TEN 60-4822WIRzzzzzz (a), TEN 60-4823WIRzzzzzz (a), TEN 60-4825WIRzzzzzz (a), TEN 60-7211WIRzzzzzz (a), TEN 60-7212WIRzzzzzz (a), TEN 60-7213WIRzzzzzz (a), TEN 60-7215WIRzzzzzz (a), TEN 60-7218WIRzzzzzz (a), TEN 60-7222WIRzzzzzz (a), TEN 60-7223WIRzzzzzz (a), TEN 60-7225WIRzzzzzz (a).

(a) - Where z= alphanumeric, "-", "/" or blank for marketing purposes.


AC/DC Power Supply

TIM 6-1211(a), TIM 6-1212(a), TIM 6-1213(a), TIM 6-1221(a), TIM 6-1222(a), TIM 6-1223(a), TIM 6-2411(a), TIM 6-2412(a), TIM 6-2413(a), TIM 6-2421(a), TIM 6-2422(a), TIM 6-2423(a), TIM 6-4811(a), TIM 6-4812(a), TIM 6-4813(a), TIM 6-4821(a), TIM 6-4822(a), TIM 6-4823(a), TIM 6-1211-A1(a), TIM 6-1212-A1(a), TIM 6-1213-A1(a), TIM 6-1221-A1(a), TIM 6-1222-A1(a), TIM 6-1223-A1(a), TIM 6-2411-A1(a), TIM 6-2412-A1(a), TIM 6-2413-A1(a), TIM 6-2421-A1(a), TIM 6-2422-A1(a), TIM 6-2423-A1(a), TIM 6-4811-A1(a), TIM 6-4812-A1(a), TIM 6-4813-A1(a), TIM 6-4821-A1(a), TIM 6-4822-A1(a), TIM 6-4823-A1(a)

AC/DC Power Supply

TPI 180-112(a), TPI 180-115(a), TPI 180-118(a), TPI 180-124(a), TPI 180-128(a), TPI 180-136(a), TPI 180-148(a), TPI 180-153(a)

Note – (a) - Stands for 6 variables, each variable may be A through Z, 0 through 9, "-", "(", ")", ".", "/" or blank



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20191120
Issue Date 2022-JUNE-27

THN 10-2410WIRzzzzzz(&), THN 10-2411WIRzzzzzz(&), THN 10-2412WIRzzzzzz(&), THN 10-2413WIRzzzzzz(&), THN 10-2415WIRzzzzzz(&), THN 10-2421WIRzzzzzz(&), THN 10-2422WIRzzzzzz(&), THN 10-2423WIRzzzzzz(&), THN 10-2425WIRzzzzzz(&), THN 10-4810WIRzzzzzz(&), THN 10-4811WIRzzzzzz(&), THN 10-4812WIRzzzzzz(&), THN 10-4813WIRzzzzzz(&), THN 10-4815WIRzzzzzz(&), THN 10-4821WIRzzzzzz(&), THN 10-4822WIRzzzzzz(&), THN 10-4823WIRzzzzzz(&), THN 10-4825WIRzzzzzz(&), THN 10-7210WIRzzzzzz(&), THN 10-7211WIRzzzzzz(&), THN 10-7212WIRzzzzzz(&), THN 10-7213WIRzzzzzz(&), THN 10-7215WIRzzzzzz(&), THN 10-7221WIRzzzzzz(&), THN 10-7222WIRzzzzzz(&), THN 10-7223WIRzzzzzz(&), THN 10-7225WIRzzzzzz(&).


(&) - z can be any alphanumeric or dash or blank

DC/DC Converter –

THN 30-2419WIR (a), THN 30-4819WIR (a), THN 30-7219WIR (a), TRV 2-0510M(a), TRV 2-0511M(a), TRV 2-0512M(a), TRV 2-0513M(a), TRV 2-0521M(a), TRV 2-0522M(a), TRV 2-0523M(a), TRV 2-1210M(a), TRV 2-1211M(a), TRV 2-1212M(a), TRV 2-1213M(a), TRV 2-1221M(a), TRV 2-1222M(a), TRV 2-1223M(a), TRV 2-1510M(a), TRV 2-1511M(a), TRV 2-1512M(a), TRV 2-1513M(a), TRV 2-1521M(a), TRV 2-1522M(a), TRV 2-1523M(a), TRV 2-2410M(a), TRV 2-2411M(a), TRV 2-2412M(a), TRV 2-2413M(a), TRV 2-2421M(a), TRV 2-2422M(a), TRV 2-2423M(a).

Switching power supply –

TPI 300-112BA-MF(a), TPI 300-115BA-MF(a), TPI 300-118BA-MF(a), TPI 300-124BA-MF(a), TPI 300-128BA-MF(a), TPI 300-136BA-MF(a), TPI 300-148BA-MF(a), TPI 300-153BA-MF(a), TPI 300-112BA-M(a), TPI 300-115BA-M (a), TPI 300-118BA-M (a), TPI 300-124BA-M (a), TPI 300-128BA-M (a), TPI 300-136BA-M (a), TPI 300-148BA-M (a), TPI 300-153BA-M (a), TPI 300-112B-MF(a), TPI 300-115B-MF(a), TPI 300-118B-MF(a), TPI 300-124B-MF(a), TPI 300-128B-MF(a), TPI 300-136B-MF(a), TPI 300-148B-MF(a), TPI 300-153B-MF(a), TPI 300-112B-M(a), TPI 300-115B-M(a), TPI 300-118B-M(a), TPI 300-124B-M(a), TPI 300-128B-M(a), TPI 300-136B-M(a), TPI 300-148B-M(a), TPI 300-153B-M(a), TPI 300-112BDR-MF(a), TPI 300-115BDR-MF(a), TPI 300-118BDR-MF(a), TPI 300-124BDR-MF(a), TPI 300-128BDR-MF(a), TPI 300-136BDR-MF(a), TPI 300-148BDR-MF(a), TPI 300-153BDR-MF(a), TPI 300-112BDR-M(a), TPI 300-115BDR-M(a), TPI 300-118BDR-M(a)



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20191120
Issue Date 2022-JUNE-27

Switching power supply –

TPI 300-124BDR-M(a), TPI 300-128BDR-M(a), TPI 300-136BDR-M(a), TPI 300-148BDR-M(a), TPI 300-153BDR-M(a), TPI 300-112A-MF(a), TPI 300-115A-MF(a), TPI 300-118A-MF(a), TPI 300-124A-MF(a), TPI 300-128A-MF(a), TPI 300-136A-MF(a), TPI 300-148A-MF(a), TPI 300-153A-MF(a), TPI 300-112A-M(a), TPI 300-115A-M(a), TPI 300-118A-M(a), TPI 300-124A-M(a), TPI 300-128A-M(a), TPI 300-136A-M(a), TPI 300-148A-M(a), TPI 300-153A-M(a), TPI 300-112-MF(a), TPI 300-115-MF(a), TPI 300-118-MF(a), TPI 300-124-MF(a), TPI 300-128-MF(a), TPI 300-136-MF(a), TPI 300-148-MF(a), TPI 300-153-MF(a), TPI 300-112-M(a), TPI 300-115-M(a), TPI 300-118-M(a), TPI 300-124-M(a), TPI 300-128-M(a), TPI 300-136-M(a), TPI 300-148-M(a), TPI 300-153-M(a), TPI 300-112DR-MF(a), TPI 300-115DR-MF(a), TPI 300-118DR-MF(a), TPI 300-124DR-MF(a), TPI 300-128DR-MF(a), TPI 300-136DR-MF(a), TPI 300-148DR-MF(a), TPI 300-153DR-MF(a), TPI 300-112DR-M(a), TPI 300-115DR-M(a), TPI 300-118DR-M(a), TPI 300-124DR-M(a), TPI 300-128DR-M(a), TPI 300-136DR-M(a), TPI 300-148DR-M(a), TPI 300-153DR-M(a).



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>

